



US MACHINE SCREW HEX NUT SIZE CHART




F - Width Across the Flats
G - Width Across Corners
H - Thickness



Nominal Number	#0	#1	#2	#3	#4	#5
Thread Per Inch (TPI) - Course		64	56	48	40	40
Thread Per Inch (TPI) - Fine	80	72	64	56	48	44
Width Across the Flats	5/32	5/32	3/16	3/16	1/4	5/16
Width Across Corners	11/64	11/64	7/32	7/32	9/32	23/64
Thickness	3/16	3/16	1/16	1/16	3/32	7/64

"Width Across the Flats" is the same as "Wrench Size"



Nominal Number	#6	#8	#10	#12
Thread Per Inch (TPI) - Course	32	32	24	24
Thread Per Inch (TPI) - Fine	40	36	32	28
Width Across the Flats	5/16	11/32	3/8	7/16
Width Across Corners	23/64	25/64	7/16	1/2
Thickness	7/64	1/8	1/8	5/32

"Width Across the Flats" is the same as "Wrench Size"

