



US HEX JAM NUT SIZE CHART




F - Width Across the Flats
G - Width Across Corners
H - Thickness



Nut Sizes	1/4"	5/16"	3/8"	7/16"
Thread Per Inch (TPI) - Course	20	18	16	14
Thread Per Inch (TPI) - Fine	28	24	24	20
Width Across the Flats	7/16"	1/2"	9/16"	11/16"
Width Across Corners	0.505"	0.577"	0.650"	0.794"
Thickness	5/32"	3/16"	7/32"	1/4"


"Width Across the Flats" is the same as "Wrench Size"




Nut Sizes	1/2"	9/16"	5/8"
Thread Per Inch (TPI) - Course	13	12	11
Thread Per Inch (TPI) - Fine	20	18	18
Width Across the Flats	3/4"	7/8"	15/16"
Width Across Corners	0.866"	1.010"	1.083"
Thickness	5/16"	5/16"	3/8"

"Width Across the Flats" is the same as "Wrench Size"

US HEX JAM NUT SIZE CHART



F - Width Across the Flats
G - Width Across Corners
H - Thickness



Nut Sizes	3/4"	7/8"	1"
Thread Per Inch (TPI) - Course	10	9	8
Thread Per Inch (TPI) - Fine	16	14	12
Width Across the Flats	1-1/8"	1-5/16"	1-1/2"
Width Across corners	1.299"	1.516"	1.732"
Thickness	27/64"	31/64"	35/64"

"Width Across the Flats" is the same as "Wrench Size"