


METRIC HEX JAM NUT SIZE CHART




F - Width Across the Flats
G - Width Across Corners
H - Thickness



Nut Sizes	M2	M2.5	M3	M4
Thread Pitch - Course [mm]	0.40	0.45	0.50	0.70
Thread Pitch - Fine [mm]	0.25	0.35	0.35	0.50
Width Across the Flats [mm]	4.0	5.0	5.5	7.0
Width Across Corners [mm]	4.62	5.77	6.35	8.08
Thickness [mm]	0.95	1.35	1.55	1.95

"Width Across the Flats" is the same as "Wrench Size"




Nut Sizes	M5	M6	M8	M10
Thread Pitch - Course [mm]	0.80	1.00	1.25	1.50
Thread Pitch - Fine [mm]	0.50	0.75	1.00	1.25
	-	-	0.75	1.00
	-	-	-	0.75
Width Across the Flats [mm]	8.0	10.0	13.0	17.0
Width Across Corners [mm]	9.24	11.55	15.01	19.63
Thickness [mm]	2.45	2.90	3.70	4.70

"Width Across the Flats" is the same as "Wrench Size"



METRIC HEX JAM NUT SIZE CHART




F - Width Across the Flats
G - Width Across Corners
H - Thickness



Nut Sizes	M12	M14	M16
Thread Pitch - Course [mm]	1.75	2.00	2.00
Thread Pitch - Fine [mm]	1.50	1.50	1.50
	1.25	1.25	1.00
	1.00	1.00	-
Width Across the Flats [mm]	19.0	22.0	24.0
Width Across Corners [mm]	21.94	25.40	27.71
Thickness [mm]	5.70	6.20	7.42

"Width Across the Flats" is the same as "Wrench Size"

METRIC HEX JAM NUT SIZE CHART



F - Width Across the Flats
G - Width Across Corners
H - Thickness



Nut Sizes	M18	M20
Thread Pitch - Course [mm]	2.50	2.50
Thread Pitch - Fine [mm]	2.00	2.00
	1.50	1.50
	1.00	1.00
Width Across the Flats [mm]	27.0	30.0
Width Across Corners [mm]	31.18	34.64
Thickness [mm]	8.42	9.10

"Width Across the Flats" is the same as "Wrench Size"